DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Yes

No

N/A

Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 1.28

WELDING INSPECTION REPORT

Resident Engineer: Casey, William **Report No:** WIR-028105 Address: 333 Burma Road **Date Inspected:** 04-Aug-2012

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 Prime Contractor: American Bridge/Fluor Enterprises, a JV

Contractor: American Bridge/Fluor Enterprises, a JV **Location:** Job Site

CWI Name: See below. **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:**

Delayed / Cancelled:

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

Quality Assurance Inspector (QA) Fritz Belford was at the American Bridge/Fluor (ABF) job site at Yerba Buena Island in California between the times noted above in order to monitor Quality Control functions and the in process work being performed by ABF personnel. The following items were observed:

OBG

This QA observed the following welders working in OBG 12W at various locations:

Authorized welder Jin Pei Wang #7299:

Welder #7299 was observed continuing on weld 12W W2.1-A1 (4G, CJP) from the previous day with welding on the deck plating underside at Y location 3800, utilizing Caltrans approved Welding Procedure Specification's (WPS) ABF-WPS-D1.5-3110-4. Welder Jin Pei Wang was also observed removing the backing bar of the weld at Y location 0 to 3000.

Authorized welder Chris Bruce #8901:

Welder #8901 was observed welding on weld 12W W2.1 PP116-BW1 (3G, CJP) panel point web complete joint penetration (CJP) weld utilizing Caltrans approved Welding Procedure Specification's (WPS) ABF-WPS-D15-1030.

Authorized welder Chang Giu Chan #2312:

Welder #2312 was observed welding on weld 12W W2.1 PP117-BW1 (3G, CJP) panel point web complete joint

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

penetration (CJP) weld utilizing Caltrans approved Welding Procedure Specification's (WPS) ABF-WPS-D15-1030.

Authorized welder Jin Quan Huang #9340:

Welder #9340 was observed welding on weld 12W 13W-B1 (3G, CJP) back gouge progressing upward utilizing Caltrans approved Welding Procedure Specification's (WPS) ABF-WPS-D1.5-1110A Rev.1.

This QA randomly observed OBG 12W QC Chris Conche, checking fit up of various welds, Magnetic Particle Inspecting (MT) back gouges and indications in weld back gouges, and WPS compliance of welders throughout the day.

Magnetic Particle Testing

This QA performed Magnetic Particle Testing (MT) on the following welds:

Weld 12W W2.1 PP116-BW1:


- 100% MT of Weld Back Gouge (630mm, MT Accept.)

Weld 12W W2.1 PP117-BW1:

- 100% MT of Weld Back Gouge (650mm, MT Accept.)

The above welds were previously accepted by QC Magnetic Particle technicians. This QA observed no rejectable indications at the time of testing. This QA Inspector generated a TL-6028 MT report on this date. The completed work observed at this location appeared to be in compliance with the contract specifications.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.





WELDING INSPECTION REPORT

(Continued Page 3 of 3)





Summary of Conversations:

Conversations relevant to work performed on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy - (510) 385-5910, who represents the Office of Structural Materials for your project.

Inspected By:	Belford,Fritz	Quality Assurance Inspector
Reviewed By:	Levell,Bill	QA Reviewer